ZITHA TECH SPECIALTY CABLES (Pty) Ltd

Fusion splicing of pre-embedded optical fibers and pigtails



Overview

Splice-on connectors can be used for initial installation of fiber links, MAC work, or repairs to existing links to minimize downtime.

Key Takeaways

Fusion splicing pre-embedded fibers to pigtails creates a permanent, low-loss optical connection by precisely aligning and melting the fiber ends together.Overview

Fusion splicing is a permanent method of joining two optical fibers using controlled thermal energy to form a continuous optical path with minimal signal loss . When working with pre-embedded fibers, the goal is to connect them to factory-terminated pigtails, which already have polished connectors on one end, leaving the other end bare for splicing . This approach ensures high-quality terminations while minimizing field polishing errors.

Required Tools and Materials
• Fusion Splicer – Uses an electric arc to melt fiber ends together, creating a seamless optical path .

• Fiber Strippers – Specialized tools to remove the outer coating without nicking the glass core .

• High-Precision Cleaver – Produces a flat, 90-degree cleave essential for low-loss splicing .

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

• Cleaning Supplies – Lint-free wipes and 99% isopropyl alcohol to remove oils and debris .

• Heat-Shrink Splice Protection Sleeves – Protects the fragile splice mechanically and environmentally .

Step-by-Step Process

• Preparation

• Strip 3–5 cm of the outer jacket and 250 µm coating from the pre-embedded fiber and pigtail .

• Clean the exposed fiber with alcohol until it is free of oils and debris .

• Cleaving

• Use a precision cleaver to create a flat, mirror-like end on both fibers .

• Inspect under a microscope to ensure proper cleave quality; angled or chipped ends increase splice loss .

• Splicing

• Place fibers in the fusion splicer's V-grooves, ensuring proper alignment .

• Activate the fusion arc to melt the fiber ends together, forming a continuous optical path .

• Modern splicers automatically align fibers and optimize arc parameters for minimal insertion loss .

• Protection

• Slide a heat-shrink splice sleeve over the joint before splicing .

• After fusion, move the sleeve over the splice and heat it in the splicer's oven to create a rigid, waterproof shield .

Best Practices

• Maintain a dust-free environment; even small contaminants can degrade performance .

• Handle fibers gently to avoid microfractures or bending beyond the minimum radius (typically >30 mm), .

• Use anti-static precautions to protect both fibers and splicer electronics .

• Inspect and test the splice with an optical power meter or OTDR to verify low insertion loss and reflectance .

Safety Considerations

• Wear safety goggles and cut-resistant gloves to protect against high-temperature arcs and glass shards .

• Dispose of fiber scraps in a dedicated container to prevent injury .

Conclusion

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Fusion splicing pre-embedded fibers to pigtails is a precise, reliable method for creating low-loss, permanent connections in optical networks. Success depends on proper fiber preparation, precise cleaving, careful alignment, and mechanical protection of the splice. Following these steps ensures long-term network integrity and optimal signal performance .

Article Content

How Do You Splice Fiber with a Fusion Splicer?

In this comprehensive guide, we will delve into when and why you need to splice fiber optic cables, discuss

How to Splice Fiber Optic Pigtails: A Step-by-Step Guide

Master the art of fiber termination. Learn how to splice fiber optic pigtails using fusion

How to Splice Fiber Optic Cable – Step-by-Step Fusion Splicing Guide

Learn how to splice fiber optic cable using fusion splicing with this complete step-by-step guide. Includes tools, best

Fiber Optic Fusion Splicing

This Cabling Installation & Maintenance sponsored Corning executive summary discusses the evolution of fiber optic fusion splicing

Fusion Splice-On Fiber Optic Connectors

Splice-on connectors can be used for initial installation of fiber links, MAC work, or repairs to existing links to minimize downtime.

Fiber Optic Pigtail: Types, Splicing Guide, Specs & Price

A fiber optic pigtail is a short fiber cable with a factory-installed connector on one end and a bare fiber end on the

October 2018 Fiber Splice-On Connectors

Introduction Single-fiber splice-on connectors are an increasingly common technology used in today''s fiber installations. These fusion

Which Fiber Termination Method is Right for You?

The good news is that as part of our comprehensive line of fiber optic solutions, Cables Plus

Preparing your Fiber Optic Cable for Connectors or Splices

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Learn the essential steps and tools for preparing fiber optic cables for connectors or

Mass Fusion Splicing: A New Approach

Regular Fusion Splicing The traditional approach to fusion splicing involves fiber pigtails (a single, short, tight-buffered

Fiber optic SC APC fast connector operation

Fast connector is a good solution to field wiring and fiber-to-the home engineering

Fusion Splice-On Fiber Optic Connectors

Fusion splice connectors also allow for higher performance links through lower insertion loss and higher return loss characteristics.

Optical Fiber Splicing: The Complete Technical Guide to

Poor fiber splicing, on the other hand, can lead to performance issues and increased maintenance costs.

What is a Fiber Optic Pigtail, and What Is It Used For?

Fiber splicing is stronger than mechanical fusion splicing, producing less loss and back

How to Terminate Fiber in Seconds

In this video, we''ll guide you through preparing and terminating fiber optic cables using

Fusion Splicing vs. Pre-Terminated Fiber Optic Cable:

Compare fusion splicing with pre-terminated fiber optic cables. Understand when to use

What is Fiber Pigtail? A Complete Guide for Beginners

A fiber pigtail is typically a fiber optic cable with one end factory pre-terminated fiber

Fiber Optic Cable Splicing Explained

Splicing is generally used to terminate single-mode fibers (by splicing pre-terminated pigtails onto each fiber) but there

How to Install Fiber Optic Pigtails (Step-by-Step Guide)

Introduction Installing fiber optic pigtails correctly is essential for ensuring low signal loss and long-term reliability.

The FOA Reference For Fiber Optics

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Many high fiber count cables today are made from ribbons of fibers, usually 12 fibers per ribbon. Splitting all those fibers out to splice

Terminating Fiber With Splice-On Connectors

Another comparison is to fusion splicing ~1 meter long pigtails on to a fiber for termination, widely used in the past for single-mode

Rise of the Splice Machines

This is a technology less than a decade old that combines the splice tray, adapter panel, pre-stripped and routed pigtails and splicing

Steps of Fusion Splicing Fiber Optic Cables

Fusion Splicing means securely connecting two optical fibers by heating their end faces and pushing them together to

Fusion Fiber Splicing Solutions | Leviton Network Solution

Splice modules, splicing pigtails and splice-on connectors have quickly become popular termination options. Leviton offers a full

Fiber Optic Pigtails, SC, FC, ST, and LC Fiber Connectors

The Fiber Optic Pigtail is normally a tight buffered fiber cable with a connector pre-terminated on one end and exposed fiber on the

The FOA Reference For Fiber Optics

Fusion splicing machines are available in two types that splice a single fiber or a ribbon of 12 fibers at one time. Virtually all

October 2018 Fiber Splice-On Connectors

Introduction Single-fiber splice-on connectors are an increasingly common technology used in today''s fiber installations. These fusion

Which Fiber Termination Method is Right for You?

The good news is that as part of our comprehensive line of fiber optic solutions, Cables Plus

Preparing your Fiber Optic Cable for Connectors or Splices

Learn the essential steps and tools for preparing fiber optic cables for connectors or

Mass Fusion Splicing: A New Approach

Regular Fusion Splicing The traditional approach to fusion splicing involves fiber pigtails (a single, short, tight-buffered

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Fiber optic SC APC fast connector operation

Fast connector is a good solution to field wiring and fiber-to-the home engineering

Fusion Splice-On Fiber Optic Connectors

Fusion splice connectors also allow for higher performance links through lower insertion loss and higher return loss characteristics.

How Do You Splice Fiber with a Fusion Splicer?

In this comprehensive guide, we will delve into when and why you need to splice fiber optic cables, discuss

How to Splice Fiber Optic Pigtails: A Step-by-Step Guide

Master the art of fiber termination. Learn how to splice fiber optic pigtails using fusion

How to Splice Fiber Optic Cable – Step-by-Step Fusion Splicing Guide

Learn how to splice fiber optic cable using fusion splicing with this complete step-by-step guide. Includes tools, best

Fiber Optic Fusion Splicing

This Cabling Installation & Maintenance sponsored Corning executive summary discusses the evolution of fiber optic fusion splicing

Fusion Splice-On Fiber Optic Connectors

Splice-on connectors can be used for initial installation of fiber links, MAC work, or repairs to existing links to minimize downtime.

Fiber Optic Pigtail: Types, Splicing Guide, Specs & Price

A fiber optic pigtail is a short fiber cable with a factory-installed connector on one end and a bare fiber end on the

Fiber Optic Pigtail: The Complete Guide to Types, Splicing Methods ...

This guide covers everything: what fiber optic pigtails are, how they differ from patch cords, which connector and

How to Splice Fiber Optic Cable: Fusion & Mechanical | DYS

How to splice fiber optic cable step by step: fusion and mechanical methods, tools, splice loss limits, OTDR verification,

Fiber Optic Fusion Splicing Guide: From Safety to Troubleshooting

Learn Fiber Optic Fusion Splicing: step-by-step guide to safe, precise fiber

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

How to Install Fiber Optic Pigtails (Step-by-Step Guide)

Align and fuse the pigtail fiber with the main cable. Apply a heat-shrink sleeve for durability. Use an OTDR or power

How Do You Splice Fiber with a Fusion Splicer?

In this comprehensive guide, we will delve into when and why you need to splice fiber optic cables, discuss

How to Splice Fiber Optic Pigtails: A Step-by-Step Guide

Master the art of fiber termination. Learn how to splice fiber optic pigtails using fusion

How to Splice Fiber Optic Cable – Step-by-Step Fusion Splicing Guide

Learn how to splice fiber optic cable using fusion splicing with this complete step-by-step guide. Includes tools, best

Fiber Optic Fusion Splicing

This Cabling Installation & Maintenance sponsored Corning executive summary discusses the evolution of fiber optic fusion splicing

Fusion Splice-On Fiber Optic Connectors

Splice-on connectors can be used for initial installation of fiber links, MAC work, or repairs to existing links to minimize downtime.

Fiber Optic Pigtail: Types, Splicing Guide, Specs & Price

A fiber optic pigtail is a short fiber cable with a factory-installed connector on one end and a bare fiber end on the

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Contact Us

Continue your research online:

Website: https://zithatech.co.za
Technical inquiry: https://zithatech.co.za/contact.html

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved